


CHAPTER 13: APPLICATIONS AND PROCESSING OF CERAMICS

ISSUES TO ADDRESS...

- **How do we classify ceramics?**
- **What are some applications of ceramics?**
- **How is processing different than for metals?**

TAXONOMY OF CERAMICS



- **Properties:**

- T_{melt} for glass is moderate, but large for other ceramics.
- Small toughness, ductility; large moduli & creep resist.

- **Applications:**


- High T, wear resistant, novel uses from charge neutrality.

- **Fabrication**

- some glasses can be easily formed
- other ceramics can not be formed or cast.

APPLICATION: REFRACTORIES

- Need a material to use in high temperature furnaces.
- Consider Silica (SiO_2) - Alumina (Al_2O_3) system.
- Phase diagram shows:
mullite, alumina, and cristobalite (made up of SiO_2) tetrahedra as candidate refractories.





Adapted from Fig. 12.27, *Callister 6e*. (Fig. 12.27 is adapted from F.J. Klug and R.H. Doremus, "Alumina Silica Phase Diagram in the Mullite Region", *J. American Ceramic Society* 70(10), p. 758, 1987.)


APPLICATION: DIE BLANKS

- **Die blanks:**
 - Need wear resistant properties!

Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.




- **Die surface:**
 - 4 μm polycrystalline diamond particles that are sintered on to a cemented tungsten carbide substrate.
 - polycrystalline diamond helps control fracture and gives uniform hardness in all directions.



Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.

APPLICATION: CUTTING TOOLS

- **Tools:**
 - for grinding glass, tungsten, carbide, ceramics
 - for cutting Si wafers
 - for oil drilling
- **Solutions:**
 - manufactured single crystal or polycrystalline diamonds in a metal or resin matrix.
 - optional coatings (e.g., Ti to help diamonds bond to a Co matrix via alloying)
 - polycrystalline diamonds resharpen by microfracturing along crystalline planes.



oil drill bits



blades



coated single
crystal diamonds




polycrystalline
diamonds in a resin
matrix.


Photos courtesy Martin Deakins,
GE Superabrasives, Worthington,
OH. Used with permission.

APPLICATION: SENSORS

- **Ex:** Oxygen sensor: ZrO_2
- **Principle:** Make diffusion of ions fast for rapid response.
- **Approach:**
 - Add Ca impurity to:
 - increase O^{2-} vacancies
 - increase O^{2-} diffusion
- **Operation:**
 - voltage difference produced when O^{2-} ions diffuse between external and reference gases.



A Ca^{2+} impurity removes a Zr^{4+} and a O^{2-} ion.




CERAMIC FABRICATION METHODS-I

GLASS FORMING


PARTICULATE FORMING

CEMENTATION


- Pressing:



- Blowing:



- Fiber drawing:




Adapted from Fig. 13.7, *Callister, 6e*. (Fig. 13.7 is adapted from C.J. Phillips, *Glass: The Miracle Maker*, Pittman Publishing Ltd., London.)


GLASS STRUCTURE

- Basic Unit:


4-
 SiO_4 tetrahedron



- Quartz is crystalline SiO_2 :



- Glass is **amorphous**
- Amorphous structure occurs by adding impurities (Na^+ , Mg^{2+} , Ca^{2+} , Al^{3+})
- Impurities: interfere with formation of crystalline structure.




(soda glass)

Adapted from Fig. 12.11,
Callister, 6e.

GLASS PROPERTIES


- **Specific volume** ($1/\rho$) vs Temperature (T):



Adapted from Fig. 13.5, Callister, 6e.


- **Crystalline materials:**
 - crystallize at melting temp, T_m
 - have abrupt change in spec. vol. at T_m
- **Glasses:**
 - do not crystallize
 - spec. vol. varies smoothly with T
 - Glass transition temp, T_g**

- **Viscosity:**
 - relates shear stress & velocity gradient:
 - has units of (Pa-s)



GLASS VISCOSITY VS T AND IMPURITIES

- Viscosity decreases with T
- Impurities lower T_{deform}



Adapted from Fig. 13.6, *Callister, 6e.*
(Fig. 13.6 is from E.B. Shand, *Engineering Glass*, Modern Materials, Vol. 6, Academic Press, New York, 1968, p. 262.)

HEAT TREATING GLASS

- **Annealing:**
 - removes internal stress caused by uneven cooling.
- **Tempering:**
 - puts surface of glass part into compression
 - suppresses growth of cracks from surface scratches.
 - sequence:


before cooling




surface cooling



further cooled



--Result: surface crack growth is suppressed.



CERAMIC FABRICATION METHODS-IIA


GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- Milling and screening: desired particle size
- Mixing particles & water: produces a "slip"
- Form a "green" component


--**Hydroplastic forming:**
extrude the slip (e.g., into a pipe)



Adapted from
Fig. 11.7,
Callister 6e.


--**Slip casting:**

pour slip
into mold



solid component


absorb water
into mold



"green
ceramic"



pour slip
into mold



hollow component

drain
mold



"green
ceramic"



Adapted from Fig.
13.10, Callister 6e.
(Fig. 13.10 is from
W.D. Kingery,
*Introduction to
Ceramics*, John
Wiley and Sons,
Inc., 1960.)


- Dry and Fire the component

FEATURES OF A SLIP

- Clay is inexpensive
- Adding water to clay
 - allows material to shear easily along weak van der Waals bonds
 - enables extrusion
 - enables slip casting


- Structure of Kaolinite Clay:

Adapted from Fig. 12.14, *Callister 6e*.
(Fig. 12.14 is adapted from W.E. Hauth, "Crystal Chemistry of Ceramics", *American Ceramic Society Bulletin*, Vol. 30 (4), 1951, p. 140.)



DRYING AND FIRING

- Drying: layer size and spacing decrease.



wet slip


partially dry

“green” ceramic

Adapted from Fig. 13.11, *Callister 6e*.
(Fig. 13.11 is from W.D. Kingery, *Introduction to Ceramics*, John Wiley and Sons, Inc., 1960.)

- Firing:
 - T raised to (900-1400 C)
 - vitrification**: glass forms from clay and flows between SiO_2 particles.

micrograph of porcelain



SiO_2 particle
(quartz)

glass formed
around
the particle

Adapted from Fig. 13.12, *Callister 6e*.
(Fig. 13.12 is courtesy H.G. Brinkies, Swinburne University of Technology, Hawthorn Campus, Hawthorn, Victoria, Australia.)


CERAMIC FABRICATION METHODS-IIB

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- **Sintering**: useful for both clay and non-clay compositions.
- **Procedure**:
 - grind to produce ceramic and/or glass particles
 - inject into mold
 - press at elevated T to reduce pore size.
- **Aluminum oxide powder**:
 - sintered at 1700C for 6 minutes.



Adapted from Fig. 13.15, *Callister 6e*.
(Fig. 13.15 is from W.D. Kingery, H.K. Bowen, and D.R. Uhlmann, *Introduction to Ceramics*, 2nd ed., John Wiley and Sons, Inc., 1976, p. 483.)

CERAMIC FABRICATION METHODS-III

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- Produced in extremely large quantities.
- Portland cement:
 - mix clay and lime bearing materials
 - calcinate (heat to 1400C)
 - primary constituents:
 - tri-calcium silicate
 - di-calcium silicate
- Adding water
 - produces a paste which hardens
 - hardening occurs due to hydration (chemical reactions with the water).
- Forming: done usually minutes after hydration begins.

SUMMARY

- **Basic categories of ceramics:**
 - glasses**
 - clay products**
 - refractories**
 - cements**
 - advanced ceramics**
- **Fabrication Techniques:**
 - glass forming (impurities affect forming temp).**
 - particulate forming (needed if ductility is limited)**
 - cementation (large volume, room T process)**
- **Heat treating: Used to**
 - alleviate residual stress from cooling,**
 - produce fracture resistant components by putting surface into compression.**